


# RM Ferrite Cores, Clamps and Bobbins

(unit: mm)


## RM4

Fig 1







Bobbin for RM4

Fig 2




CLAMPS




## RM5

Fig 1







Bobbin for RM5

Fig 2




CLAMPS




## RM6

Fig 1







Bobbin for RM6


Fig 2



Clamps







## RM8




Bobbin for RM8



## RM 8



# RM10



Bobbin for RM10



ITEM	AlnH ± 25%							
	JP40	J2M	J2	J4	J4	J5	J6	J7
RM4 F1	1000	1450						
RM4 F2	900	1000	1050			1400		
RM5 F1			2000					
RM5 F2	1250 MIN	2000	2200					
RM6 F1	2100	2000	2300	2900	3500			
RM8	2800	2800	3500	4400	5000			
RM10	4400	4400	5200	6000	7000			